

Loss Prevention Supplement

Dealing with • ENGINE TOOM TITES

Introduction

By **Peter Stålberg** Senior Technical Advisor

Over the last 10 years, between 2008 and 2017, The Swedish Club received 28 reports concerning engine room fires. When compared to other Hull and Machinery (H&M) claims the frequency of engine room fires is low but the average cost is among the highest - USD 1,850,000 per occurrence - compared with USD 320,000 for H&M claims in general.

Engine rooms on ships have all the ingredients for a fire – oxygen, heat and flammable liquids under pressure. Not surprisingly, one of the dominating causes is lube-oil or fuel-oil mist spraying onto hot surfaces and then igniting



Peter Stålberg, Senior Technical Advisor at The Swedish Club, explains: "The SOLAS requirements concerning oil piping in engine rooms are clear; all types of oil pipes must be screened and flanges protected so that any eventual leak will not spray onto a hot surface. Any surface with a temperature above 220°C must be thermally insulated."



All vessels today are required to have double containment piping (jacketing) for high pressure oil piping. Any leakage inside the containment will be lead to a small collecting tank thus giving the operator early warning of a problem. Any other fuel piping should be screened.

At new build the insulation of the exhaust pipe system - including the turbo-chargers - is normally in good

About Peter Stålberg

Peter Stålberg returned to The Swedish Club as Senior Technical Advisor, two years ago, after spending nine years working in the offshore sector.

Prior to that he previously worked for the Club from 1993 to 2008 in various roles including Technical Manager, Staff Surveyor, Director Technical and Risk Assessment, and Area Manager.

With an expertise in marine engineering and risk assessment, Peter's priorities are to ensure efficiency in the way the Club works, and to make sure that the Loss Prevention team maintains focus on the key issues affecting shipping today.

condition. "Over time, however, when overhauling engine room machinery and removing/refitting exhaust pipes, the insulation will deteriorate," explains Stålberg. "An exhaust pipe system insulated to 95% is not good enough – it must be 100% intact – always."

Poorly insulated exhaust pipe

Dealing with an engine room fire

Preventing an engine room fire is the priority, but the time and effectiveness of the response is almost as important. Although a crew has taken all reasonable precautions, an engine room fire can still occur without warning.

"In one case I was involved with," says Stålberg, "even though the exhaust gas pipes on the vessel were insulated with thick blankets of insulation and covered with metal sheets, spraying oil from a sheared hydraulic oil pipe, which found its way to the hot exhaust gas pipe under the insulation, through the crevices and ignited. Quick action by the crew controlled the fire and minimised the damage.

Preventing an engine room fire is the priority, but the time and effectiveness of the response is almost as important

"A swift and effective response within a few minutes may limit the damage, to soot washing and less than USD 200,000 in costs. Yet I have seen cases where delaying the response or failing to operate the fire extinguishing system properly, has allowed the fire to intensify and spread, causing severe damage and cost in excess of USD 3,000,000.

"In the following articles we take a look at three different engine room fires – could they have been avoided? Were they dealt with properly? And could they happen on your ship?"





The PSV Brann

Interview with Angelo Santos

Chief Engineer of the Platform Supply Vessel Brann

We were heading for an offshore unit to discharge cargo. The weather was not good - the wind speed was about 30 knots with a swell of about 4 metres – but we were all experienced and knew what we were doing.

I was told later that at about 1850 the fire alarm had sounded on the bridge, and the Master, who was on the bridge at the time, saw smoke coming from the funnel ventilation on the port side. He immediately set off the general alarm.

Meanwhile I was in the engine control room when the fire alarm sounded and so I left the room to see what was happening. There was a fire around the top covers of cylinders #2/#3 of the port side main engine.

I tried to put out the fire with a portable fire extinguisher, but it was too bad and so I went back to the engine control room, activated the fire alarm button and contacted the Master on the bridge.

Other members of the crew came to assist and we tried to enter the engine room again to put out the fire, but the flames were very high with a great deal of smoke and so we could not get near it. We decided it was time to release the CO_2 bottles of the fixed system and flood the engine room.

I closed all the fire dampers and activated the remote quick closing valves for the fuel system. I then went into the CO_2 fixed system release station with the electrical engineer. We opened the cabinet door and automatically the CO_2 release alarm sounded and the ventilation fans stopped. We then started on the steps needed to perform the CO_2 release.

However, whilst we were going through this process I must have missed opening one of the valves and no CO_2 was released. As soon as I realised this I used the manual handle to open the CO_2 bottles. Unfortunately I found out later that only seven CO_2 bottles from a total of thirteen were released into the engine room.

After releasing the ${\rm CO_2}$, we were pleased to see that the amount of smoke coming from the engine room through the funnel ventilation was decreasing. However very soon the amount of smoke increased again.

At this point we realised that the CO_2 system had not worked as we had hoped and that we had to abandon the vessel. We launched the two starboard side life rafts and one of the port side life rafts, but found that we couldn't abandon ship on that side because the weather was too bad and it was not safe. Two members of the crew managed to get into the first starboard life raft when the safety line broke. The other fourteen of us made it into the second life raft.

Luckily we were all rescued within 20 minutes of abandoning the Brann.

The cost of the casualty was USD 2,400,000.







The MV Vatria

Interview with **Captain Sven Carlsblad**Master of the Container Vessel Vatria

We were en route to Salalah. All evening I had been receiving reports of alarms being activated due to high levels in some of the fuel leakage collecting tanks.

The first alarm went off at 1630 followed by a second alarm ten minutes later. Shortly afterwards the first alarm went off again twice. After this it did not return to normal status.

At 2320 my Chief Engineer reported an automatic slowdown of the main engine. At the same time I saw heavy smoke coming into the bridge from the funnel area. This was caused by a fire in the engine room. The fire alarms were activated followed by an automatic shutdown of the main engine and engine room ventilation fans.

At 2330 I mustered the crew and all were found present with no injuries. The Chief Engineer went into the fire station and shut the quick closing valves and released CO₂ into the engine room. He then cut off electrical power in the engine room and closed the skylight and all ventilation flaps.

At that point we sent an undesignated distress relay via INM C and MF-HF giving the location position of the Vatria, and I contacted our Company DPA (Designated Person Ashore).

The crew rigged the fire hoses and began cooling the boundary and monitoring temperatures in the engine room. The VDR incident back up was activated and we carried on cooling the boundary and keeping in touch with the manager's emergency team.


When the temperature had gone down from 52°C to 41°C my Chief Officer led the firefighting team to the engine room skylight where they could see that the fire had been extinguished. As no fire was visible they thought it safe to go into the engine room through the aft emergency exit. The team then came out of the engine room and confirmed that the fire had been put out, at which point the hoses were turned off.

We restarted the engine room ventilation at 1418 and the firefighting team used gas detectors to sample the engine room atmosphere – they declared it safe with no more fire hazard.

Following this we restarted the two auxiliary engines and restored partial power in the engine room. Electrical power was restored to all the reefer containers and I sent the crew to manually monitor reefer temperatures.

We were without main engine power for six days until a tug arrived to tow us to port.


The intensity of the fire caused significant smoke, heat and fire damage to the engine room and the equipment within it. The insurance claim was in the region of USD 3,500,000.



Cause

The survey concluded that the main cause of the fire in the engine was related to the failure of the aft fuel oil high pressure pipe of unit No. 4. The pipe had fractured and severed completely at the thrust bushing at the fuel pump side.

According to the information provided by the ship's staff it is unknown if the correct tightening pressure of 190 Nm was applied as recommended in the MAN service instruction manual.





The MV Fuoco

Interview with Franco Pueblo

Chief Engineer of the Bulk Carrier Fuoco

We were on a ballast passage to Durban, South Africa and crossing a high pirate risk area. The No. 2 auxiliary engine was in operation and providing our electrical power requirements with the No. 3 auxiliary engine acting as the standby.

At 0845 hours we lost all electrical power, followed by the main engine shutting down. Our emergency generator started automatically, and at the same time the 'fire in engine room' alarm started, followed by the general alarm and other engine room alarms.

I hurried to the engine room where I saw smoke and fire coming from the auxiliary generator platform on the third deck level. The engine room team said that the No.2 auxiliary engine had caught fire – this was quickly spreading and they couldn't control it. They had tried to put out the fire by using portable fire extinguishers, but without any luck.

I grabbed a portable CO₂ fire extinguisher but couldn't get near the auxiliary engine platform due to the intense heat, flames and smoke. In the end we were

forced to evacuate the engine room.

Immediately we mustered the crew and were relieved to find nobody missing and no casualties.

I then went with the Master to the remote control station outside of the engine room, and we activated the fuel oil quick closing valves, closed the fire dampers and stopped the engine room ventilation fans. At 0900 exactly we set off the engine room's CO₂ fire extinguishing system which released the contents of one hundred and one cylinders of CO₂ into the engine room. 30 minutes later the emergency firefighting team went into the engine room from the upper deck entrance and reported that the fire had been extinguished.

We checked the fire damaged area when it was safe to do so, and the engine room was declared all clear. We restored ventilation at 0950 hours and at 1040 hours the engine room was manned.

The insurance claim was in the region of USD 450,000.



Cause

The fire was caused by the diesel oil fuel duplex filter vent screw vibrating loose. This allowed a high pressure stream of fuel to come in to contact with the deck head above the operating auxiliary engine No.2.

When the stream of fuel made contact with the deck head, the diesel oil spread over the turbocharger exhaust outlet casing and the hot exhaust protection covers of the auxiliary engine, creating the vapour to spontaneously ignite. The full pressure of the diesel oil leaking from the vent hole continued to feed the fire.

Once the fire broke out it rapidly spread, overheating and melting the various components within the automation control panel which was fitted directly behind the auxiliary engines on the third deck level. This meant that the backup automatic start sequence of the standby auxiliary engine was not possible.

Viewpoint: Peter Stålberg

In this case, the crew did a proper job extinguishing the fire. They managed to release the contents of all 101 $\rm CO_2$ cylinders into the engine room; 30 minutes later the team went into the engine room, and the situation was under control.

This was a good response. The crew were trained and they knew how to deal with the situation. It's important to remember that even if you follow all the rules and regulations, you can still have fires – you can't foresee everything – and that is why training is so necessary.

As to the cause, we have seen similar cases where a vent screw or sampling point has vibrated open. It could be that when someone has changed filters or taken samples, they quickly fastened the screw by hand and forgot to tighten it properly later. This would be the result of a poor maintenance routine – a checklist would have eliminated this hazard.

This was a good response. The crew were trained and they knew how to deal with the situation.



Loss prevention

Loss prevention is at the heart of everything we do

It saves lives It protects the environment It delivers onboard efficiencies



Lars A. MalmDirector, Strategic Business
Development & Client Relations



Joakim Enström Loss Prevention Officer



Peter Stålberg Senior Technical Advisor

Our goal is to contribute to an enhanced marine safety culture and we know that being a step ahead is paramount when it comes to preventing accidents. The Swedish Club puts a great deal of effort into loss prevention analysis and knowledge-sharing with its members and the shipping community.

We learn from incidents that have taken place, and endeavour to prevent them reoccurring by working with our members to offer them guidance and training initiatives:

Training

- Emergency Response Training
- · Stress Test Drill
- Monthly Safety Scenario
- Maritime Resource Management (MRM)

Initiatives

- The Swedish Club Philippine Pre Engagement Medical Examination (PEME)
- Swedish Club Operations Review (SCORE)
- Benchmarking
- Awareness campaigns

Information

- Member Alerts
- Loss prevention publications
- Loss prevention guidance

Our complete portfolio of loss prevention solutions can be found at:

www.swedishclub.com/loss-prevention

